

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst Executive Engineer)

(Re: G.O. Ms 20/70/PWD Dt 23-01-1970)

Name of the School:

Sainik Public School

1. Name of the officer : Sheeba A.S (PEN-691189)
2. Location : Naduvath PO-679328, Wandoor, Malappuram
3. Period for which the certificate issued : 2024-25
4. Types of building : Sheet Roof with false ceiling
F/Floor- 3x7.50 M x 6.05 M x 3.70M (3 Class Rooms)
F/Floor-1x30.50 M x2.00M x 3.70M (Verandah)
5. Nature of defect if any :
 - (a) Foundation and basement :
 - (b) Super structure :
 - (c) Doors and windows :
 - (d) Wood work wrought and put up: NIL
 - (e) Roof :
 - (f) Flooring :
 - (g) Miscellaneous (Cracks if any) :
6. Any major defects notices which will : NIL
render the building unsafe in any manner
7. Whether maintenance works have : New Building
been done properly
8. Whether the structure is sound or not : Yes, Sound to conduct classes under normal
for Conducting classes wind and weather conditions

- Note:-**
1. The stability of the structure should be examined also with reference to location altitude intensity of wind exposure or flood etc.
 2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

CERTIFICATE

Certified that the School was inspected by me on 05/06/2024 and found to be fit/unfit to conduct classes for the period 2024-25 for the reason stated above.

Place: Wandoor

Date: 07/06/2024



.....
(Assistant Executive Engineer)

LSGD (LID&EW) Subdivision
Wandoor Block Panchayath
PEN.

TO BE FILLED BY THE INSPECTING OFFICER

(Assistant Engineer)

No.10/AE/LSGD/TLY/FC/24-25, Dated 31.05.2024

- Name of the School : **SAINIK PUBLIC SCHOOL**
- 1 Name of the Officer : **FRANCIS.A.FERNANDEZ**
- 2 Location : **Naduvath,**
: **Wandoor Education District**
: **Wandoor Education Sub District.**
- 3 Period for which the Certificate is issued : **2024-25**
- 4 Types of Building :
- | | | | |
|------------------|----|---|---|
| 1) RCC Building | GF | : | 1 x 50.35 x 8.70 x 3.70 (7 Classrooms) |
| | FF | : | 1 x 50.35 x 8.70 x 3.70 (7 Classrooms) |
| GI Sheet Roofing | SF | : | 4 x 6.25 x 6.60 x 3.60 (Ave) (4 Classrooms) |
| Verandah | | : | 1 x 29.25 x 1.50 |
| 2) RCC Building | GF | : | 1 x 30.80 x 8.70 x 3.30 (3 Classrooms) |
- 5 Nature of Defect if any
- | | | |
|----------------------------------|---|-------|
| a) Foundation and Basement | : | } Nil |
| b) Super structure | : | |
| c) Doors and windows | : | |
| d) Wood work wrought and putup | : | |
| e) Roof | : | |
| f) Flooring | : | |
| g) Miscellaneous (Cracks if any) | : | |
- 6 Any Major defects noticed which will render the building unsafe in any manner : **Not noticed**
- 7 Whether maintenance work have been done properly : **Yes**
- 8 Whether the structure is sound or not for conducting classes : **Sound to conduct classes under normal wind and weather conditions as on 31.05.2024 as far as could be seen externally.**


- Note:-
- 1 The Stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood etc..
 - 2 Any additional observation if deemed necessary for the certificate may be furnished separately with the Certificate

Certified that the School was inspected by me on **31.05.2024** and found to be **FIT** to conduct classes for the period for the reason stated above.

Place: Thiruvalli
Date: 31.05.2024



Signature
Designation


FRANCIS. A. FERNANDEZ
ASSISTANT ENGINEER (PEN: 703049)
LSGD SECTION, THIRUVALI
PH: 9446 984 795